


Centre Belt Connections


Connecting methods for centre belt



NOS
No extra material in flat areas. NOS rods are most used under joining clips.



KS clip
For diameters:
9 | 10 | 11 | 12



H-Pintle Clamp
For H-Pintle webs with 3 or more centre belts.



Highflex
Extra material added in flat areas, in vertical direction, making the area higher and stronger.



WB clip

Belts 50 mm	CTC 20	Rod 10 mm
Belts 50 mm	CTC 20	Rod 8 mm
Belts 60-75mm	CTC 32	Rod 10 mm
Belts 60-75 mm	CTC 30	Rod 11 mm
Belts 60-75 mm	CTC 30	Rod 11 mm
Belts 60-75 mm	CTC 32	Rod 11 mm
Belts 60-75 mm	CTC 32	Rod 12 mm



4-lips Clamp
For webs with 12x6 strips / rods with 3 or more centre belts.




Superflex
Extra material added in flat areas, in horizontal direction, making the area wider and stronger.



P clip

Belts 20 mm	1 Hole	Rod 8 mm
Belts 20 mm	1 Hole	Rod 10 mm
Belts 20 mm	1 Hole	Rod 11 mm
Belts 20 mm	1 Hole	Rod 12 mm
Belts 30 mm	1 Hole	Rod 11 mm



3-lips Clamp
For V-Pintle webs with 3 or more centre belts.